

Work Order ID 130588

130588

Page 1

Tuesday, March 17, 2015 9:20:51 AM

Item ID: D206-642-314

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 3/17/2015 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: MLS Date: 1503-17

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Run Start *NR1*

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

IIN-D206-642

Q

100

Document Control

0.00

DAS
27
9-89

100

DOCUMENT CONTROL

DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile and create labels per PPP D206-642-314 CHG001

MLJ done
18 2015
DAS
02
9-89

JUL 13 2015

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

IX
DAS
27
9-89
JUN 18 2015

DAS
28
9-89

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.00

Quality Control

DAS
02
9-89

JUL 13 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other		

Work Order ID 130588***130588***

Page 2

Tuesday, March 17, 2015 9:20:51 AM

Item ID: D206-642-314

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 3/17/2015 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							02 9-89
130	Packaging								
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D206-642-314								
	Location: <u>083</u>								JUL 14 2015
	PPP Rev: _____								
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.00							<u>MLJ</u> JUL 14 2015
Quality Control									

MLJ JUL 14 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
		☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge
		☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other

Picklist Print

Tuesday, March 17, 2015 9:20:56 AM

Page 1

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A 11.11.18 NEW ISSUE DD VERF:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D206-642-351

Manufactured

No

110

Each

0.0000

1

1

D206-642-351

DAS

**

130583

DAS
6

Replacement Skidtube, Low & High Gear, Run-on Landing Wearplates Fits LH or RH

D206-648-013

9-89

Manufactured

No

110

Each

18.0000

1

1

D206-648-013

DAS

**

DAS
27
9-89

DAS
26
9-89

Ground Handling Wheel Modification

DAS
02
9-89

Location

Loc Qty

Loc Code

PKG013

18

115114

5

127607

1

127608

2

128931

4

128932

2

129959

4

B131063

1

D2932-2

Manufactured

No

110

Each

10.0000

1

1

D2932-2

**

DAS
26
9-89

Saddle RH Out, 206

DAS
02
9-89

Location

Loc Qty

Loc Code

ST392

4

114497

4

ST396

4

125059

4

ST403

2

121757

1

125656

1

B132374

1

DAS
27
9-89

JUN 18 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design ☐									
Doc/Data ☐									
Equip/Tooling ☐									
Handling/Pre ☐									
Material ☐									
Operator ☐									
Offset/Setup ☐									
Process ☐									
Supplier ☐									
Training ☐									
Transport ☐									
Unapproved ☐									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence	☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
--	--	---	--

Picklist Print

Tuesday, March 17, 2015 9:20:56 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

D2933-2 Manufactured No

110 Each 6.0000 1 1

D2933-2

Saddle RH In, 206

**

DAS
26
9-89

DAS
27
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

ST389

5

114499

5

ST396

1

125657

1

B13239S

1

D2938-2 Manufactured No

110 Each 8.0000 1 1

D2938-2

Saddle RH Out, 206

**

DAS
26
9-89

DAS
27
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

ST390

3

114500

3

ST395

4

123741

4

ST403

1

125658

1

B135783

1

D2939-2 Manufactured No

110 Each 11.0000 1 1

D2939-2

Saddle RH In, 206

**

DAS
26
9-89

DAS
27
9-89

JUN 28 2015

DAS
02
9-89

Location

Loc Qty

Loc Code

ST391

4

114501

4

ST395

5

122887

1

125098

4

ST396

1

121748

1

ST403

1

125659

1

B13241S

1

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other		

Picklist Print

Tuesday, March 17, 2015 9:20:56 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

AN3-41A

Purchased

No

110

Each

825.0000

8

8

AN3-41A

Bolt

**DAS
02
9-89**

Location

Loc Qty

Loc Code

FG

20

122416

20

ST338a

794

123355

794

ST347

11

123355

11

D2652

Manufactured

No

110

Each

697.0000

16

16

D2652

Bushing

**DAS
02
9-89**

Location

Loc Qty

Loc Code

FG

45

31985

45

ST012a

652

123711

32

124422

3

128778

4

129992

312

129993

301

B1327D

16

**DAS
26
9-89**

**DAS
27
9-89**

**DAS
27
9-89**

JUN 18 2015

**DAS
26
9-89**

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence	☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
--	--	---	--

Picklist Print

Tuesday, March 17, 2015 9:20:57 AM

Page 4

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

110

Each

2,341.000

8

8

MS21042L3

Nut

DAS
02
9-89

**

DAS
27
9-89

DAS
26
9-89

Location

Loc Qty

Loc Code

FP001

420

M130922

420

GA

844

M131317

844

ST305

1077

116549

14

126333

275

M131264

57

M131624

731

M130123

8

NAS1149D0363J

Purchased

No

110

Each

2,636.000

8

8

NAS1149D0363J

Washer



DAS
02
9-89

**

DAS
27
9-89

DAS
26
9-89

Location

Loc Qty

Loc Code

CA

569

m130799

569

FP001

2

113288

2

GA

406

m128429

406

ST269

1659

m131616

1659

8

JUN 18 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
		☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge
		☐ Pressure/Forced Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other

Picklist Print

Tuesday, March 17, 2015 9:20:57 AM

Page 5

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

AN5-10A

Purchased

No

110

Each

243.0000

4

4

AN5-10A

BOLT

DAS
02
9-89

Location

Loc Qty

Loc Code

GA

51

122800

51

ST338

192

M131305

2

M131624

190

**

DAS
27
9-89

DAS
26
9-89

AN5-12A

Purchased

No

110

Each

21.0000

4

4

AN5-12A

Bolt

DAS
02
9-89

Location

Loc Qty

Loc Code

ST338

21

M128606

6

M131624

15

**

DAS
27
9-89

DAS
26
9-89

AN5-11A

Purchased

No

110

Each

165.0000

8

8

AN5-11A

BOLT

DAS
02
9-89

Location

Loc Qty

Loc Code

ST299A

165

M126105

165

**

DAS
27
9-89

DAS
26
9-89

JUN 18 2015

Tuesday, March 17, 2015 9:20:57 AM

Shop Packet Print

Page 5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other		

Picklist Print

Page 6

Tuesday, March 17, 2015 9:20:57 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

NAS1149D0563J

Purchased

No

110

Each

1,087.000

8

8

NAS1149D0563.J

Washer

**

DAS
27
9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

GA	130	
m125807	130	
ST260a	68	
113524	3	
118206	2	
m130799	63	
ST269	156	
m128257	156	
ST271	733	
m131026	733	

m132035

8

AN4-6A

Purchased

No

110

Each

2,514.000

12

12

AN4-6A

BOLT

**

DAS
27

JUN 18 2015

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

CA	143	
M128403	43	
M130851	100	
ST325A	1599	
M131153	1599	
ST345	772	
M128403	8	
M128634	764	

12

Tuesday, March 17, 2015 9:20:57 AM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence	☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
--	--	---	--

Picklist Print

Tuesday, March 17, 2015 9:20:57 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

NAS1149D0463J

Purchased

No

110

Each

3,958.000

24

24

NAS1149D0463.I

WASHER

**

DAS
27
9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

CA

397

M129682

397

GA

162

M129390

162

ST269

3399

M130799

507

M131624

2892

132035x2

m132317

2x22

MS21042L4

Purchased

No

110

Each

2,819.000

12

12

MS21042I 4

Locknut

**

DAS
27
9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

FP001

42

m124231

42

GA

644

m127813

644

ST260a

1140

m130799

56

m131340

1084

ST305

993

426

426

m128300

8

m128798

4

m130922

97

m131618

458

m132123

b

JUN 18 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
--	--	---

Picklist Print

Tuesday, March 17, 2015 9:20:57 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

D3407-043

Manufactured No

110

Each

20.0000

1

1

D3407-043

Tow Ring

DAS
02
9-89

Location

Loc Qty

Loc Code

st530

14

120517

5

123729

9

ST532

6

114527

6

**

DAS
27
9-89

~~DAS
26
9-89~~

D3456-1

Manufactured No

110

Each

116.0000

1

1

D3456-1

Washer

DAS
02
9-89

Location

Loc Qty

Loc Code

FG

7

25701

7

ST040

59

121045

9

129861

50

ST051A

50

128456

50

**

DAS
27
9-89

~~DAS
26
9-89~~

D3457-1

Manufactured No

110

Each

50.0000

2

2

D3457-1

Washer

DAS
02
9-89

Location

Loc Qty

Loc Code

FG

10

32409

10

ST040

40

121777

10

127393

18

129758

12

**

DAS
27
9-89

~~DAS
26
9-89~~

JUN 18 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other		

Picklist Print

Tuesday, March 17, 2015 9:20:57 AM

Page 9

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

MS21043-4

Purchased

No

110

Each

1,468.000

1

1

MS21043-4

Nut

**

DAS

27

9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

FG

40

104603

40

GA

432

m128798

432

ST304

996

m128798

162

m128818

34

m131697

800

M132382

AN4C5A

Purchased

No

110

Each

94.0000

1

1

AN4C5A

Bolt

**

DAS

27

9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

FP001

13

M128403

13

ST345

41

M130466

41

ST346

40

131677

40

NAS1149C0463R

Purchased

No

110

Each

384.0000

1

1

NAS1149C0463R

Washer

**

DAS

27

9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

FP001

94

m127306

94

ST271

290

m128401

290

JUN 18 2015

Tuesday, March 17, 2015 9:20:57 AM

Shop Packet Print

Page 9

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
		☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge
		☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other

Picklist Print

Page 10

Tuesday, March 17, 2015 9:20:57 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

D3413-1 Manufactured No

110 Each 50.0000 1 1

D3413-1

O-Ring

DAS
02
9-89

Location

Loc Qty

Loc Code

FP001

1

121783

1

st530

49

110715

9

114489

4

125157

12

127411

8

129085

16

B132500

**

DAS
27
9-89

DAS
26
9-89

D2712 Manufactured No

110 Each 769.0000 10 10

D2712

Set Screw

DAS
02
9-89

Location

Loc Qty

Loc Code

FG

55

29962

55

ST009

264

115155

240

121858

4

124450

20

ST012a

450

127910

250

130024

200

**

DAS
27
9-89

JUN 18 2015

DAS
26
9-89

Tuesday, March 17, 2015 9:20:57 AM

Shop Packet Print

Page 10

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Crosstube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐
--	--	---

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence
		☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge
		☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other

Picklist Print

Page 11

Tuesday, March 17, 2015 9:20:57 AM

Work Order ID: 130588

130588

Parent Item: D206-642-314

D206-642-314

Parent Item Name: Skidtube RH, Low & High Gear with Run-on Landing Wearplates

Start Date: 3/17/2015

Required Date: 3/17/2015

Start Qty: 1.00

Required Qty: 1.00

D2934

Manufactured No

110

Each

79.0000

2

2

D2934

Saddle Spacer

**

DAS
27
9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

FG

6

31929

6

ST025A

73

121765

25

123631

8

128810

40

D2935

Manufactured No

110

Each

56.0000

2

2

D2935

Saddle Spacer

**

DAS
27
9-89

DAS
26
9-89

DAS
02
9-89

Location

Loc Qty

Loc Code

FG

6

31793

6

ST014

15

120514

15

ST025A

35

121970

35

B13107

JUN 18 2015

Tuesday, March 17, 2015 9:20:57 AM

Shop Packet Print

Page 11

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Crosstube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>	Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐															
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐															
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐															
Large Fab ☐	Composite ☐	Supplier ☐																

Root Cause	Date	Step	Qty	Description of work order update or non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Design									
Doc/Data									
Equip/Tooling									
Handling/Pre									
Material									
Operator									
Offset/Setup									
Process									
Supplier									
Training									
Transport									
Unapproved									

FAULT CATEGORY

Landing Gear ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Inspection Strip in Tube ☐ Marks/Chatter ☐ Turning Sequence ☐ Wave/Twist in Tube	General ☐ Bend ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Burrs ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Drawing ☐ Drill Holes ☐ Finish ☐ Fit/Function	☐ Folio/Program ☐ Grain ☐ Hardware ☐ Inspection Incomplete/Unqualified ☐ Instructions Incomplete/Unclear ☐ Misaligned/off center ☐ Mislabeled ☐ Misread ☐ Off-set ☐ Out of Calibration ☐ Out of Sequence	☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Positioned Wrong ☐ Power Loss/Surge ☐ Pressure/Forced ☐ Set-up ☐ Temperature/Cure ☐ Weld ☐ Wrong Stock Pulled ☐ Other
--	--	---	--

4.5 206 L/L-1/L-3/L-4/407 LOW & HIGH GEAR SKIDTUBES

ITEM	QTY -311	QTY -312	QTY -313	QTY -314	QTY -341	QTY -357	QTY -349	QTY -351	QTY -013	PART NUMBER	DESCRIPTION
	X									D206-642-311	SKIDTUBE INSTALLATION, LH
		X								D206-642-312	SKIDTUBE INSTALLATION, RH
			X							D206-642-313	SKIDTUBE INSTALLATION, LH
				X						D206-642-314	SKIDTUBE INSTALLATION, RH
1	1	1			X					D206-642-341	SKIDTUBE
						X				D206-642-357	WEARSHOE KIT (REPLACES -347)
							X			D206-642-349	RUN-ON LANDING WEARPLATE KIT
			1	1				X		D206-642-351	SKIDTUBE
1	1	1	1	1					X	D206-648-013	GROUND HANDLING KIT
1					1					D2650-5	SKIDTUBE ASSEMBLY
1								1		D4361-041	SKIDTUBE ASSEMBLY
2A					14			4		D2651-1	* PLUG ⁽¹⁾
2B					14			4		D2651-3	* O-RING ⁽¹⁾
3					1			1		D2646	* AFT CAP ⁽¹⁾
4					2			2		MS27039-1-08	* SCREW ⁽¹⁾
5					2			2		NAS1149D0332J	* WASHER ⁽¹⁾ (OR AN960JD10L)
6	1		1							D2932-1	SADDLE, FWD OUT, LH
6		1		1						D2932-2	SADDLE, FWD OUT, RH
7	1		1							D2933-1	SADDLE, FWD IN, LH
7		1		1						D2933-2	SADDLE, FWD IN, RH
8	1		1							D2938-1	SADDLE, AFT OUT, LH
8		1		1						D2938-2	SADDLE, AFT OUT, RH
9	1		1							D2939-1	SADDLE, AFT IN, LH
9		1		1						D2939-2	SADDLE, AFT IN, RH
10	8	8	8	8						AN3-41A	BOLT
11	16	16	16	16						D2652	BUSHING
12A	8	8	8	8						MS21042-3	NUT (OR MS21042L3)
12B	8	8	8	8						NAS1149D0363J	WASHER (OR AN960JD10)
13	4	4	4	4						AN5-10A (OR AN5-11A)	* BOLT ⁽²⁾
14	4	4	4	4						AN5-11A (OR AN5-12A)	* BOLT ⁽²⁾
15	8	8	8	8						NAS1149D0563J	WASHER (OR AN960JD516)
16	12	12	12	12						AN4-6A	BOLT
17	24	24	24	24						NAS1149D0463J	WASHER (OR AN960JD416)
18	12	12	12	12						MS21042-4	NUT (OR MS21042L4)
20A					6	6				D3537-1	WEARPAD (REPLACES D2648-3)
21A					1	1				D3537-3	WEARPAD (REPLACES D3429-1)
22A					1	1				D4956-11	WEARSHOE (REPLACES D3535-11 + D3536-11)
23A					1	1				D4956-23	WEARSHOE (REPLACES D3535-23 + D3536-23)
24A					1	1				D4956-35	WEARSHOE (REPLACES D3535-35 + D3536-35)
26A					54	54				MS27039C1-08	SCREW
26B					54	54				NAS1149C0332R	WASHER (OR AN960C10L)
26C					54					ALS7-1032-130	* INSERT ⁽¹⁾ (or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
30	1	1	1	1						D3407-043	TOW RING ASSEMBLY (REPLACES D2968-043)
32A	1	1	1	1						D3456-1	WASHER
32B	2	2	2	2						D3457-1	WASHER
33	1	1	1	1						MS21043-4	NUT
34	1	1	1	1						AN4C5A	BOLT
35	1	1	1	1						NAS1149C0463R	WASHER (OR AN960C416)
36	1	1	1	1						D3413-1	RING (REPLACES D2655)
37	10	10	10	10						D2712	SET SCREW
38	2	2	2	2						D2934	SADDLE SPACER
39	2	2	2	2						D2935	SADDLE SPACER
40									2	D3414-041	GHW LUG (REPLACES D2659)
41									4	AN3C37A	BOLT
42									8	D2652	BUSHING
43									4	MS21043-3	NUT
44									4	NAS1149C0363R	WASHER (OR AN960C10)

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC. •
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
 OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: **Q**
 Date: 13.08.12